



City of Bryant – Mills Park Pool

Swimming Pool Repair Quotation

Swimming Pool Resurfacing

Summary: Resurface existing swimming pool with new plaster surface. Excludes any tile replacement.

Scope of Work

- Pressure wash / Acid Wash existing pool surface
- Cut back along water line
 - 2" saw cut and demo of existing plaster around all existing tile/skimmer
- Cut back along all waterline tile – existing tile to remain
- Sound test floor / walls to ensure surface integrity – remove all failed plaster
 - 500 sqft allotted for
 - Excess square footage priced at \$1.00/sqft
- Repair any cracked areas with high strength patching material
- Install cementitious coating to create proper surface bond - BondKote
- Install 1/2" to 5/8" of plaster surface material
 - Marble Dust & Portland Cement Plaster surface (8-12 year service life)
- Fill pool & add startup chemicals during fill to harden plaster surface and to remove metals of fill water.
- Includes clean up and removal of debris

Cost: \$44,300⁰⁰ plus applicable sales tax

Special Considerations:

- 1. Filling of pool must be continuous. Owner accepts responsibility for any damage / stain rings of plaster if water pressure is lost and / or water is shut off before pool is completely full.*
- 2. A “metal out” chemical will be added to fill process to coagulate metals that are present in fill water to prevent staining of plaster surface. Owner accepts responsibility for any staining of new plaster surface caused by excessive metals deposited onto plaster surface during fill process and or make-up water added to pool during normal operations.*

Warranty Information

Bluewater CAS will provide a two (2) year labor and material warranty on all items installed / repaired by Bluewater CAS. All other manufacturer warranties apply. For warranty to be extended to the swimming pool surface, proper water chemistry and working water level must be documented and maintained.